Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE0060/1

Work Order Type: Weatherization Audit Name: Audit DE0060

CLIENT INFORMATION

Client Name: Address:

Client ID: Client 50005DE0060

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Measures

M	easure 1 Pa	tch 1' x 3' floor area at fr	ont door		Componen	ts		1	Inspected
Co	mment								
					Estimated			Actual	
# /	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 l	Jnspecified	Misc Material	Each	1					
Oti	her Detail								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:								
	longuro 2 Do	nois 41 y 21 osoo in don oo	-:::		Componen	40			Inspector
	easure 2 Re mment	pair 1' x 3' area in den ce	eiling		Componen				Inspected
Co	mment		_	Qtv	Estimated		Qtv	Actual	Inspected
C o		pair 1' x 3' area in den ce Description / Comment Misc Material	eiling Units Each	Qty 1	•		Qty		
Co # / 10 l	mment Material / Labor Jnspecified	Description / Comment	Units	_	Estimated		Qty	Actual	
Co # <i>I</i> 10 l	mment Material / Labor	Description / Comment	Units	_	Estimated		Qty	Actual	
Co # <i>I</i> 10 l	mment Material / Labor Jnspecified	Description / Comment	Units	_	Estimated		Qty	Actual	
Co # <i>I</i> 10 l	mment Material / Labor Jnspecified	Description / Comment	Units Each	1	Estimated			Actual	
# / 10 U	mment Material / Labor Unspecified her Detail	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	
# / 10 U	mment Material / Labor Jnspecified	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	
# / 10 U	mment Material / Labor Unspecified her Detail	Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	

Measure 3 Rep	oair 2' x 2' area in bedroo	m ceiling	9	Componen	ts		ı	nspect
Comment				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
			_	Unit Cost	IOlai	Qiy	Unit Cost	TOLAI
Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes: Measure 4 Reg	place broken pane at W9			Componen	ts			nspect
Measure 4 Rep	place broken pane at W9			Componen				nspecte
Measure 4 Rep	·			Estimated			Actual	
Measure 4 Rep	Dlace broken pane at W9 Description / Comment	Units	Qty	•		Qty		nspecto
Measure 4 Rep Comment Material / Labor	·	<i>Units</i> Each		Estimated		Qty	Actual	
Measure 4 Rep Comment Material / Labor Unspecified	Description / Comment			Estimated		Qty	Actual	
Measure 4 Rep Comment Material / Labor Unspecified	Description / Comment			Estimated		Qty	Actual	
Measure 4 Rep Comment Material / Labor Unspecified	Description / Comment			Estimated		Qty	Actual	
	Description / Comment	Each	1	Estimated			Actual	

Measure 5 Re	place window facings at	W14, W1	6	Componen	ts		ı	nspect
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
Caror Dotain								
			Measur	e Sub Total:]	Sub Total:	
						1		
	place window sills at W1	2, W13, V	V1,	Componen	ts		,	nspect
Measure 6 Re W2		2, W13, V	V1,	·				nspect
Measure 6 Re W2 Comment				Estimated	<u>'</u>	Ofv	Actual	Inspecto
Measure 6 Re W2 Comment # Material / Labor	Description / Comment	Units	Qty	·		Qty		
Measure 6 Re W2 Comment # Material / Labor 0 Unspecified				Estimated	<u>'</u>	Qty	Actual	
Measure 6 Re W2 Comment # Material / Labor	Description / Comment	Units	Qty	Estimated	<u>'</u>	Qty	Actual	Total
Measure 6 Re W2 Comment # Material / Labor 0 Unspecified	Description / Comment	Units	Qty	Estimated	<u>'</u>	Qty	Actual	
Measure 6 Re W2 Comment # Material / Labor 0 Unspecified	Description / Comment	Units	Qty	Estimated	<u>'</u>		Actual	

Measure 7 Inf	iltration Redctn			Componen	its			Inspected
1.Add 3. Bloo 5. Add	nment AIR INFILTRATION MEASURES 1.Add threshold Garage and bac 3. Block and Seal A/C W3 5. Add Doorsweep - Garage and 6. Add Weatherstriping - Garage							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
Measure 8 DV	VH Tank Insulation			Componen				Inspected
Measure 8 DV Comment				Estimated	1		Actual	
Measure 8 DV Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected
Measure 8 DV Comment # Material / Labor		<i>Units</i> Each		Estimated	1	Qty	Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment	Description / Comment		Qty	Estimated	1	Qty	Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated	1		Actual	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
Measure 8 DV Comment # Material / Labor 1 Hot Water Equipment 2 Labor Other Detail	Description / Comment DHW Tank Insulation	Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure 9 Re	place A/C			Componen	ts AC		ı	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipme	ent Window A/C -	Each	1					
2 Labor	Window A/C -	Each	1					
Other Detail						1 [
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 10 DW	/H Pipe Insulation			Componen	ts		ı	Inspected
	/H Pipe Insulation			Componen Estimated			Actual	Inspected
	/H Pipe Insulation Description / Comment	Units	Qty	-		Qty		Inspected
Comment	·	<i>Units</i> Each		Estimated		Qty	Actual	
Comment # Material / Labor	Description / Comment		Qty	Estimated		Qty	Actual	
# Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

	c Ins. R-38			Componer	nts 1776	SQ.FT	1	Inspecte
	OWNER HAS ADDED A F SULATION - JUST OLD R			OVER EN	TIRE HOU	JSE -		
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1776					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Comment HOME RECOI	Diace Htg. System OWNER HAS TWO UNVENTED TO THE MIND REPLACING WIT		AS SP		•) BTU I	heaters	Inspecte
	HEATER AND REMOVING			•		ED	Actual	
# Material / Labor				ONE		ED 	Actual Unit Cost	Total
	HEATER AND REMOVING	G THE SE	COND	ONE Estimate	d			Total
1 Heating Equipment	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 -	G THE SE Units	Qty	ONE Estimate	d			Total
1 Heating Equipment	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	G THE SE <i>Units</i> Each	Qty 1	ONE Estimate	d			Total
1 Heating Equipment 2 Labor	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	G THE SE <i>Units</i> Each	Qty 1	ONE Estimate	d			Total
1 Heating Equipment 2 Labor	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	G THE SE <i>Units</i> Each	Qty 1	ONE Estimate	d			Total
1 Heating Equipment 2 Labor	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	Units Each Each	1 1	ONE Estimate	d	Qty		Total
Heating Equipment Labor	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	Units Each Each	1 1	ONE Estimate Unit Cost	d	Qty	Unit Cost	Total
1 Heating Equipment 2 Labor Other Detail	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	Units Each Each	1 1	ONE Estimate Unit Cost	d	Qty	Unit Cost	Total
2 Labor Other Detail	Description / Comment Space Heater - 15 kBtu/h NG Existing, 47 - 66 kBtu/h NG Post Space Heater - 15 kBtu/h NG Existing, 47 -	Units Each Each	1 1	ONE Estimate Unit Cost	d	Qty	Unit Cost	Total

Page 7 of 10

Measure 13 Flo	or Ins. R-19		Components old trailor					Inspected
Comment BELLY	OF OLD TRAILOR							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	600					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	oor Ins. R-19 DDITION SECTIONS HAVE IS TERMITE DAMAGE F		LAR EX		OOR JO		· •	Inspected
Comment THE A	DDITION SECTIONS HAV		LAR EX	XPOSED FL	OOR JO		Actual	Inspected
Comment THE A	DDITION SECTIONS HAV		LAR EX	XPOSED FL	OOR JO		· •	Inspected Total
Comment THE A	DDITION SECTIONS HAVE IS TERMITE DAMAGE F	PRESENT	LAR EX	XPOSED FL	OOR JO	IST -	Actual	
Comment THE A THERE # Material / Labor	DDITION SECTIONS HAVE IS TERMITE DAMAGE F Description / Comment Floor Insulation -	PRESENT <i>Unit</i> s	LAR EX	XPOSED FL	OOR JO	IST -	Actual	
Comment THE A THERE # Material / Labor 1 Insulation	DDITION SECTIONS HAVE IS TERMITE DAMAGE F Description / Comment Floor Insulation -	PRESENT <i>Unit</i> s	LAR EX	XPOSED FL	OOR JO	IST -	Actual	
Comment THE A THERE # Material / Labor 1 Insulation	DDITION SECTIONS HAVE IS TERMITE DAMAGE F Description / Comment Floor Insulation -	PRESENT <i>Unit</i> s	LAR EX	XPOSED FL	OOR JO	IST -	Actual	
Comment THE A THERE # Material / Labor 1 Insulation	DDITION SECTIONS HAVE IS TERMITE DAMAGE F Description / Comment Floor Insulation -	Units SqFt	Qty 900	XPOSED FL	OOR JO	Qty	Actual	

Report Run On: 5/23/2010

1	<i>l</i> leasure 15 CO l	Monitor is Needed			Componen	ts			Inspecte
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
C	ther Detail								
Ĭ									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 16 Fix I	mproper Venting (Cloth	hes Drver)	Componen	ts			Inspecte
	Measure 16 Fix I	mproper Venting (Cloth	nes Dryer)	Componen				Inspecte
C	omment				Estimated		Ofv	Actual	
C #	omment Material / Labor	Description / Comment	Units	Qty	•		Qty		
C #	omment				Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety	Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	Total
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	Total
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated			Actual	
C # 1	Material / Labor Health and Safety Items Labor ther Detail	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Report Run On: 5/23/2010

	or Barrier Needed ement/Crawlspace)			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						,		
			Measur	e Sub Total:			Sub Total:	
	ed Vent-A-Hood to Inc	lude Firdo	own	Componen	ts			Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	
1 Health and Safety Items	Material	Each	1					Total
2 Labor								Total
	Labor	Each	1					Total
Other Detail	Labor	Each	1					Total
Other Detail	Labor	Each	1					Total
Other Detail	Labor	Each	1					Total
Other Detail	Labor			e Sub Total:			Sub Total:	Total

Report Run On: 5/23/2010